

State of Utah

Department of **Natural Resources**

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

Representatives Present During the Inspection:								
C	ompany	Dennis Oakley Environmental Engineer						
	OGM	James L. Dykmann Deputy State Historic Preserva						

Inspection Report

Permit Number:	C0150017		
Inspection Type:	PARTIAL		
Inspection Date:	Thursday, July 28, 2005		
Start Date/Time:	7/28/2005 7:59:00 AM		
End Date/Time:	7/28/2005 9:08:00 AM		
Last Inspection:	Tuesday, June 28, 2005		

Inspector: Jim Smith, Environmental Scientist III

Weather: Clear, dry, warm InspectionID Report Number: 682

Accepted by: whedberg

8/3/2005

Permitee: PACIFICORP

Operator: ENERGY WEST MINING CO

Site: **DES BEE DOVE MINE**

Address: PO BOX 310, HUNTINGTON UT 84528

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	154.86
Total Disturbed	23.88
Phase I	
Phase II	
Phase III	

Mineral Ownership **Types of Operations**

	•	• • •
✓ Federal		✓ Underground
✓ State		Surface
☐ County		Loadout
✓ Fee		Processing
Other		Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Little noticeable change since last inspection. Vegetation is maturing, Russian thistle is larger, more apparent. XTO has moved the proposed coal-bed-methane well location to the reclaimed pump house area.

Inspector's Signature

Date

Friday, July 29, 2005

Jim Smith, Environmental Scientist III Inspector ID Number: 43

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Thursday, July 28, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓			
3.	Topsoil				
4.a	Hydrologic Balance: Diversions				
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading		✓		
13.	Revegetation	✓		✓	
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing				
16.	Roads: Drainage Controls				
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150017 Inspection Type: PARTIAL

Inspection Date: Thursday, July 28, 2005 Page 3 of 3

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Dennis Oakley indicated there had been some flow to the pond from a recent storm, but the water and level appeared to be lower than during the last inspection. The second quarter pond inspection report was not completed at the time of the inspection. Dennis said he will start pumping water from the pond next week.

4.d Hydrologic Balance: Water Monitoring

UPDES discharge from the sedimentation pond is the only water monitored at this site. The June UPDES report showed No Discharge. There has been no discharge reported or known so far in 2005.

4.e Hydrologic Balance: Effluent Limitations

UPDES discharge from the sedimentation pond is the only water monitored at this site. The June UPDES report showed No Discharge.

9. Protection of Fish, Wildlife and Related Environmental Issues

Rabbits and birds were seen in the reclaimed area during the inspection.

13. Revegetation

Vegetation is maturing, Russian thistle is larger, more apparent.